

Dials and Specials

Description


Marsh Bellofram offers customers the option of choosing their own gauge dial format.

This service compliments the comprehensive range of professionally manufactured quality products that are available.

Marsh Bellofram is able to design and print full colour dials to their customers exact specifications.

These options may incur an extra cost or a minimum quantity depending on the item chosen please contact the office where a member of the sales team will discuss the options available.

Our wide variety of options insure that you will find the perfect fit for your application.



Conversion Chart

Unit	BAR	mBAR	kPa	psi	In.H ₂ O	MmHg	In.Hg	Kg/cm ²
1 BAR	1	1000	100	14.5038	401.463	750.064	29.53	1.01972
1mBAR	0.001	1	0.1	0.0145	0.40146	0.75006	0.02953	0.00102
1 kPa	0.01	10	1	0.14504	4.01463	7.50064	0.2953	0.0102
1 psi	0.06895	68.9476	6.89476	1	27.6799	51.7151	2.03602	0.07031
1 In.H ₂ O	0.00249	2.49089	0.24909	0.03613	1	1.86833	0.07356	0.00254
1 mmHg	0.00133	1.33322	0.13332	0.01934	0.53524	1	0.03937	0.00136
1 In.Hg	0.03386	33.8639	3.38639	0.49115	13.5951	25.4	1	0.03453
1Kg/cm ²	0.98067	980.665	98.0665	14.2233	393.701	735.561	28.959	1

Temperature Conversion $C \times 1.8 + 32 = ^\circ F$ $(F - 32) : 1.8 = ^\circ C$